

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

697600064**FIELD INSPECTION FORM**Loc ID 319351 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243318	WELL	SI	01/01/2018	GW	123-11109	MONFORT GILCREST K 8-8	EI
420427	WELL	PR	08/01/2018	GW	123-32581	FIVE RIVERS K 08-22D	EI
420429	WELL	PR	08/01/2018	GW	123-32582	FIVE RIVERS K 08-07D	EI
420431	WELL	PR	08/01/2018	GW	123-32583	FIVE RIVERS K 08-17D	EI

**General Comment:**[production facilities not co-located with wells and battery not inspected in this report.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: <u>243318</u>	Type: <u>WELL</u>	API Number: <u>123-11109</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>420427</u>	Type: <u>WELL</u>	API Number: <u>123-32581</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>420429</u>	Type: <u>WELL</u>	API Number: <u>123-32582</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>420431</u>	Type: <u>WELL</u>	API Number: <u>123-32583</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT