

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

679703942

**FIELD INSPECTION FORM**

Loc ID 316401 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone | Email                           | Comment    |
|--------------------|-------|---------------------------------|------------|
| Energy, Foundation |       | regulatory@foundationenergy.com | Regulatory |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                 | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 272751      | WELL | SI     | 02/01/2017  | GW         | 103-10447 | COLUMBINE SP FED 13C-23-4-104 | SI          |

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 5/2/2019 at approximately 13:30, inspector Rick Moran, conducted a follow up inspection at Foundation Energy Management's well Columbine Springs Federal 13C-23-4-104 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679703545 and FIRR document 402019287.

During this inspection the following compliance issues were identified as resolved:

- 1) Tank label.
- 2) Battery sign.

This is a summary of inspection report 679703942.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                              | #   |       | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Deadman # & Marked          | # 4 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Pig Station                 | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Gas Meter Run               | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type          | Tank ID | SE GPS                |
|--------------------|---|----------|---------------|---------|-----------------------|
| PRODUCED WATER     | 1 | <50 BBLS | BV FIBERGLASS |         | 39.701980,-109.044940 |
| Comment:           |   |          |               |         |                       |
| Corrective Action: |   |          |               | Date:   |                       |

|                  |          |
|------------------|----------|
| <b>Paint</b>     |          |
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 40 bbl   |
| Other (Type)     |          |

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| <b>Berms</b>       |          |                     |                     |             |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |    |  |       |
|--------------------|----|--|-------|
| <b>Venting:</b>    |    |  |       |
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Flaring:</b>    |  |  |       |
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 272751 Type: WELL API Number: 103-10447 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 679703943    | inspection photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814160">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814160</a> |