

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

688304502**FIELD INSPECTION FORM**Loc ID 320745 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10646Name of Operator: AXIS EXPLORATION LLCAddress: 370 17TH ST SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Extraction	720-370-5540	COGCCInspections@extractionog.com	
Rickard, Jeff	720-557-08310	jrickard@extractionog.com	
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204773	WELL	TA	08/28/2018	GW	005-06858	COLUMBINE-STATE 1	TA

**General Comment:**SI/TA UIC, passed

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	LO/TO		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	tank battery not inspected					
Corrective Action:						Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance



**Inspected Facilities**Facility ID: 204773 Type: WELL API Number: 005-06858 Status: TA Insp. Status: TA**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Submit Form 4 for SI/TA well status. Form 21 attached (not signed by operator yet) and needs to be submitted by operator electronically within 10 days of test.  
 Anytime Well Testing, ~2 bbls to load hole, some air in well, Crystal gauge  
 Casing and Tubing on slight vacuum to begin test, down to 0 psi  
 0 min 375 psi  
 5 min 373 psi  
 10 min 372 psi  
 15 min 372 psi  
 -3 psi lost  
 Casing 0 psi after test, tubing blew down to 0 psi immediately  
 Bradenhead was plumbed to surface and dead (valve verified open).

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304582	Axix Columbine-State 1 well and sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814174">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814174</a>
688304583	Axix Columbine-State 1 well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814175">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814175</a>
688304584	Axix Columbine-State 1 Crystal gauge	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814176</a>
688304585	Axix Columbine-State 1 Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814177">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4814177</a>