

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2019

Submitted Date:

05/03/2019

Document Number:

679703961**FIELD INSPECTION FORM**Loc ID 315628 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231188	WELL	PR	03/09/1995	GW	103-08857	DIAMOND-SHAMROCK-FEDERAL 1-5	PR

**General Comment:**

COGCC Inspection Report Summary.

On 5/3/2019 at approximately 11:00, inspector Rick Moran, conducted a follow up inspection at Lasso Oil &amp; Gas's well Diamond Shamrock Federal 1-5 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679703130.

During this inspection the following compliance issues were identified as resolved:

- 1) Weeds in pit.
- 2) Missing wellhead sign.
- 3) Nearest public road.

This is a summary of inspection report 679703961.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-209-9762

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	231188	Type:	WELL	API Number:	103-08857	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:				Date:					

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat: 39.819070                      Long: -108.637210

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date: \_\_\_\_\_

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat: 39.819100                      Long: -108.637290

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Inspector Name: Moran, Rick

Comment:		Date:
Corrective Action		
Anchor Trench Present:                      Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>YES</u>		
Comment:		Date:
Corrective Action		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703962	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815095</a>