

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2019

Submitted Date:

05/03/2019

Document Number:

679703971

FIELD INSPECTION FORM

Loc ID 316103 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232120	WELL	PR	10/01/1995	GW	103-09791	FEDERAL 12-5	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 5/3/2019 at approximately 16:00, inspector Rick Moran, conducted a follow up inspection at Utah Gas's well Federal 12-5 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679701637 and Form 42 document 401847005.

During this inspection the following compliance issues were identified as resolved:
1) Unused containers.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703971.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Bird Protectors		# 1		
Comment:				
Corrective Action:			Date:	
Deadman # & Marked		# 1		
Comment:				
Corrective Action:			Date:	
Gas Meter Run		# 1		
Comment:				
Corrective Action:			Date:	
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<50 BBLs	Open Top		39.800400,-108.685900

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 232120 Type: WELL API Number: 103-09791 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703972	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815099