

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2019

Submitted Date:

05/04/2019

Document Number:

679703969

**FIELD INSPECTION FORM**

Loc ID 315402 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 54290  
Name of Operator: MASTORAKOS\* D A  
Address: 195 DRAKEWOOD PLACE  
City: NOVATO State: CA Zip: 94947

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230776	WELL	SI	11/11/2009	GW	103-08445	FEDERAL 11-1	SI

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 5/3/2019 at approximately 15:00, inspector Rick Moran, conducted a follow up inspection at D A Mastorakos well Federal 11-1 in Rio Blanco county.

While there I conducted a follow up inspection of:

- 1) FIR document 675103008 dated 10-13-2016.
- 2) FIR document 679701635 dated 11-5-2018.
- 3) Warning letter 2193177 dated 2-6-2016.

During this inspection the following compliance issues were observed as uncompleted:

- 1) No well head sign. Photo 3.
- 2) Missing nearest public road on battery sign. Photo 4.
- 3) Missing emergency contact number on battery sign. Photo 4.
- 4) Weeds next to building and in pit. Photo 2 and 5.
- 5) No MIT.

Locks are on 2 of 3 well head valves. The gas meter chart inside the building is dated 11-10-2011. There is no email address on record for the operator. An internet search indicates Dimitrios A. Mastorakos of Novato, CA died 5-8-2015.

This is a summary of inspection report 679703969.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Missing nearest public road.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No sign at well head.		
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	Sign not posted or information inaccurate at well(s) or battery. Emergency phone number missing.		
Corrective Action:			Date:

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds next to buildings and in pit.		
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:			Date:

**Equipment:**

Type:		#		corrective date
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:				Date:
Deadman # & Marked		# 4		
Comment:				
Corrective Action:				Date:
Bird Protectors		# 1		
Comment:				
Corrective Action:				Date:
Gas Meter Run		# 1		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230776 Type: WELL API Number: 103-08445 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No current MIT on record or delinquent as required by Rule 326.  
Last recorded production November 2009. No MIT on recorded.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration, erosion, or soil movement on location.

Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: \_\_\_\_\_ Pit ID: \_\_\_\_\_ Lat: 39.796700 Long: -108.690600

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action  Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703970	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815216">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815216</a>