

Caerus Piceance LLC
Api # 05-045-11594
Inspection # 696600039



Photo at entrance to location. No tank battery sign at time of inspection

Caerus Piceance LLC
Api # 05-045-11594
Inspection # 696600039



Tank Battery , No tank battery sign at time of inspection.



Well head

Caerus Piceance LLC
Api # 05-045-11594
Inspection # 696600039



Holes in Tank Containment liner.



More holes in tank liner.

Caerus Piceance LLC
Api # 05-045-11594
Inspection # 696600039



Hole in berm causing storm water to not be controlled

Opposite side of hole in berm, shows a heavy erosions channel and sediment gathering in bottom by fence, off location. .