

Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



**Photo 1. Overview of location taken at entrance facing northeast.**

Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



**Photo 2. Silt fence compromised.**




**Photo 3. Silt fence compromised.**



Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



**Photo 4. Silt fence compromised.**



**Photo 5. Silt fence compromised. Sediment leaving location.**



Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



**Photo 6. Silt fence compromised.**



**Photo 7. Silt fence compromised. Sediment leaving location.**



Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



**Photo 8. Silt fence compromised.**



**Photo 9. Uncovered additives.**

Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



**Photo 10. Uncovered additives.**



**Photo 11. Uncovered additives.**



Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



Photo 12. Cuttings area, cuttings leaving area.



Photo 13. Cuttings area.

Inspection Photos  
Location Name: Patriot 0880 13-32H5  
API: 05-057-06618



Photo 14. Cuttings area.



Photo 15. Cuttings area, cuttings leaving area.