

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2019

Submitted Date:

05/06/2019

Document Number:

689802625**FIELD INSPECTION FORM**Loc ID: 449274 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449275	WELL	PR	06/01/2018		057-06598	REU 0681 1-23H2	PR

General Comment:**COGCC Inspection Report 689802625 Summary**

On Friday 05/03/2019 at approximately 13:30 I, Inspector Emily Waldron, conducted a field inspection at Sandridge Exploration and Production LLC Rabbit Ears 0681 23, Location ID 449274, in Jackson County, Colorado. Inspection was stormwater focused and in direct response to observation of vehicle tracking onto Colorado State Highway 14.

During this inspection the following possible compliance issues were observed:

Access road is washed out from recent heavy precipitation events. No BMPs or operator response observed. Vehicle tracking occurring off of location and onto Colorado State Highway 14 for approximately 0.6 miles north of location. See photos 1-10.

Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority by 5/6/2019. Install or repair required BMPs per Rule 1002.f by 5/8/2019.

I spoke with Aaron Cook of Sandridge by phone on 05/03/2019 and continued vehicle tracking was discussed.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689802625.

Inspected Facilities									
Facility ID:	449275	Type:	WELL	API Number:	057-06598	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Access road is washed out from recent heavy precipitation events. No BMPs or operator response observed. Vehicle tracking occurring off of location and onto Colorado State Highway 14 for approximately 0.6 miles north of location.

Corrective Action: Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority. Install or repair required BMPs per Rule 1002.f.

Date: 05/06/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802629	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816238