

## Inspection Photos

Location Name: IRISH EYES 33-21

API #: 05-071-08658

INSP. #:695100599



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE **Install sign to comply with Rule 210.b.**

## Inspection Photos

Location Name: IRISH EYES 33-21

API #: 05-071-08658

INSP. #:695100599



**PHOTO 3: CULVER ON ROW NORTHWEST OF LOCATION IS PLUGGED. Install or repair required BMPs per Rule 1002.f.**

**PHOTO 4: SEDIMENT HAS FILLED STORMWATER DRAIN ON UPSLOPE SIDE OF PLUGGED CULVERT**

## Inspection Photos

Location Name: IRISH EYES 33-21

API #: 05-071-08658

INSP. #:695100599



**PHOTO 5: SEDIMENT HAS CAUSED STORMWATER TO CROSS ROAD JUST INFRONT OF CULVERT**

**PHOTO 6: STORMWATER EROSION AROUND CULVERT OUTLET. *Install or repair required BMPs per Rule 1002.f.***