



**Location**

Overall Good:

**Signs/Marker:**

	Type OTHER		
Comment:	PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	07/06/2019

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 4: IMPACTED SOIL NEAR WELLHEAD NO LEAK OBSERVED AT TIME OF INSPECTION		
Corrective Action:	Comply with Rule 603.f .	Date:	06/06/2019

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

			corrective date
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

**Venting:**

Yes/No NO

Comment:

Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 263049 Type: WELL API Number: 071-07602 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 264928 Type: PIT API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 264928      Lat: 37.064425      Long: -104.683243

Reference Point: SE      Other: \_\_\_\_\_      Length: 20      Width: 20

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: NO

Comment: **PHOTO 3: PIT IS PULL ALMOST RUNNING OVER THE EDGE. THERE IS NO 2' FREEBOARD MARKER.**

Corrective Action

**Lower fluid level so at least two feet of freeboard exists per Rule 902.b. INSTALL FREEBOARD MARKER.**

Date: 05/07/2019

Permit:	Facility ID	Permit Num	Expiration Date
	264928	1121040	
	264928	1121040	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100602	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816279">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816279</a>