

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2019

Submitted Date:

05/07/2019

Document Number:

696100846

**FIELD INSPECTION FORM**

Loc ID 319423 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

**Findings:**

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>
Cowan, Peter		picowan@blm.gov	<a href="#">BLM; federal/federal inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243445	WELL	PR	12/01/2018	OW	123-11236	MONAHAN FEDERAL 24	SI

**General Comment:**

[This is a WELL & BATTERY Inspection.](#)  
[1-Well: SI](#)  
[Battery: In Operation](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	<p>From prior FIR:                      Observed stained soil below crude oil tank load out and signs of prior seepage from load out threads.                      Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (30 Days).                      Remediate or remove stained soil below crude oil tank load out and crude oil seepage stains from load out threads. Ensure that threads no longer leak. Comply w/ Rule 605.d.                      Corrective Action date: 05/17/2019.                      This FIR:                      * Stained soil below crude oil tank load out and signs of prior seepage from load out threads appear to be mitigated.                      See photos #3, 4.</p>		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tanks VOCs. Pilots: ON		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.389018,-104.381523
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ produced H2O vault.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		Shares berms w/ crude oil tank.			
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 243445 Type: WELL API Number: 123-11236 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Observed production valves shut.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On MON MAY 06, 2019 at approximately 14:09 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: Bonanza Creek Energy Operating Company LLC.                      Location Name: MONAHAN FEDERAL-65N63W /24NWNE.                      Location ID: 319423                      Location County: Weld County, Colorado</p> <p>While there, I observed: 1-Well(s) SI &amp; Battery (In Operation).                      Follow-up Inspection.                      Follow-up to FIR #696100790 dated 04/17/2019.                      1 of 1: Corrective Actions addressed.                      1.) Observed stained soil below crude oil tank load out and signs of prior seepage from load out threads.                      Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (30 Days).                      Remediate or remove stained soil below crude oil tank load out and crude oil seepage stains from load out threads. Ensure that threads no longer leak. Comply w/ Rule 605.d.                      Corrective Action date: 05/17/2019.                      * Stained soil below crude oil tank load out and signs of prior seepage from load out threads appear to be mitigated.                      See photos #3, 4.</p> <p>NO: Corrective Actions observed on this FIR.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/06/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100847	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816632">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4816632</a>