

Inspection Photos
Location Name: Loehr Larry R#1
Location ID: 322864



Photo 1 PU and WH



Photo 2 TNK BTRY

Inspection Photos
Location Name: Loehr Larry R#1
Location ID: 322864



Photo 3 Stained soil inside containment appears to be removed.



Photo 4 Stained soil under recir pump appears to be removed and 1 ECD running and other shut in.

Inspection Photos
Location Name: Loehr Larry R#1
Location ID: 322864



Photo 5 Sep/meter house



Photo 6 bull plug installed.