

## Inspection Photos

Location Name: UPTOWN FEDERAL 22-27

API #: 05-071-06725

INSP. #:695100605



Colorado Oil & Gas Conservation Commission  
37.23282, -104.66133, 2165.0m, 265°  
2019/05/07 10:27:48

**PHOTO 1: LOCATION**



Colorado Oil & Gas Conservation Commission  
37.23283, -104.66147, 2176.0m, 4°  
2019/05/07 10:27:55

**PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS  
INACCURATE Install sign to comply with Rule 210.b. CA DUE DATE  
7/7/19**

## Inspection Photos

Location Name: UPTOWN FEDERAL 22-27

API #: 05-071-06725

INSP. #:695100605



**PHOTO 3: TRASH NEAR METER HOUSE. COMPLY WITH RULE 210.b. CA DUE DATE 5/17/19**



**PHOTO 4: TRASH OFF THE EAST EDGE OF LOCATION. COMPLY WITH RULE 210.b. CA DUE DATE 5/17/19**



## Inspection Photos

Location Name: UPTOWN FEDERAL 22-27

API #: 05-071-06725

INSP. #:695100605



**PHOTO 5: UNUSED EQUIPMENT. COMPLY WITH RULE 603.f.  
CA DUE DATE 6/7/19**



**PHOTO 6: UNUSED EQUIPMENT OFF SOUTHEAST EDGE OF  
LOCATION. COMPLY WITH RULE 603.f. CA DUE DATE 6/7/19**



## Inspection Photos

Location Name: UPTOWN FEDERAL 22-27

API #: 05-071-06725

INSP. #:695100605



**PHOTO 7: IMPACTED SOIL NEXT TO WELLHEAD BENEATH DRIVEHEAD MOTOR.** Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 6/7/19



**PHOTO 8: IMPACTED SOIL ON WEST SIDE OF ENGINE SKID.** Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 6/7/19



## Inspection Photos

Location Name: UPTOWN FEDERAL 22-27

API #: 05-071-06725

INSP. #:695100605



Colorado Oil & Gas Conservation Commission  
37.23284, -104.66177, 2184.0m, 43°  
2019/05/07 10:30:37



Colorado Oil & Gas Conservation Commission  
37.23284, -104.66178, 2186.0m, 14°  
2019/05/07 10:30:41

**PHOTO 9: IMPACTED SOIL ON SOUTH SIDE OF ENGINE SKID.** Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. **CA DATE 6/7/19**

**PHOTO 10: IMPACTED SOIL ON WEST SIDE OF ENGINE SKID.** Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. **CA DATE 6/7/19**