

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2019

Submitted Date:

05/07/2019

Document Number:

695100605**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 307649 Beardslee, Tom 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217946	WELL	PR	02/01/2018	GW	071-06725	UPTOWN 22-27	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE		
Corrective Action:	Install sign to comply with Rule 210.b. CA DUE DATE 7/7/19	Date:	06/06/2019

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 7: IMPACTED SOIL NEXT TO WELLHEAD BENEATH DRIVEHEAD MOTOR. PHOTO 8: IMPACTED SOIL ON WEST SIDE OF ENGINE SKID. PHOTO 9: IMPACTED SOIL ON SOUTH SIDE OF ENGINE SKID. PHOTO 10: IMPACTED SOIL ON WEST SIDE OF ENGINE SKID.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	06/07/2019
Type	TRASH		
Comment:	PHOTO 3: TRASH NEAR METER HOUSE. PHOTO 4: TRASH OFF THE EAST EDGE OF LOCATION.		
Corrective Action:	COMPLY WITH RULE 210.b. CA DUE DATE 5/17/19	Date:	05/17/2019
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: UNUSED EQUIPMENT. PHOTO 6: UNUSED EQUIPMENT OFF SOUTHEAST EDGE OF LOCATION.		
Corrective Action:	COMPLY WITH RULE 603.f.	Date:	06/07/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	DRIP		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 217946	Type: WELL	API Number: 071-06725	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	270543	1126318	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100606	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817401