

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2019

Submitted Date:

05/07/2019

Document Number:

685100917**FIELD INSPECTION FORM**
 Loc ID 319714 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J.B.		jbcrog@aol.com	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Canfield, Chris		chris.canfield@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccenforcement@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	

Data retrieval failed for the subreport, 'Subreport3'.

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil on load lines in back of both crude oil tanks and water tank see pic 3&10		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	11/19/2018
Type	OTHER		
Comment:	Stained soil, possible leak on manifold. see pic 7		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/07/2019
Type	OTHER		
Comment:	Stained soil and possible leak in separator house, buckets of what appears to be crude oil, no containment see pic 6		
Corrective Action:	"For localized spotting of oily waste - ""Properly treat or dispose of oily waste in accordance with 907.e.""  For larger instances: ""Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS""	Date:	05/09/2019
Type	OTHER		
Comment:	Valves leaking on load out lines in back of crude oil tanks see pic 3		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	11/19/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:		Electric motor	Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		39.847880,-104.274490
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.847880,-104.274490
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	201072	Type:	WELL	API Number:	001-06475	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 113216Lat: 39.849193Long: -104.275232Reference Point: SE

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**Fencing Type: None

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

No netting on produced water tank, hydrocarbon sheen appears to be visible on water see pic 8,9,11. No wildlife mortality was observed at time of inspection.

Corrective Action

Net or fence pit to prevent access per rule 902.d.

Date: 05/14/2019

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/7/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at Ferguson 2-25 at 001-06475 Renegade Oil &amp; Gas in Adams County Colorado.</p> <p>While there, I observed Producing well.</p> <p>This is a follow up inspection from document # 688400438</p> <p>1 CA was addressed (produced water capacity label) all other CA from previous inspection appear to be delinquent as of 11/19/18</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Valves leaking on load out lines in back of crude oil tanks see pic 3</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 11/19/18</p> <p>Stained soil on load lines in back of both crude oil tanks and water tank see pic 3&amp;10</p> <p>Properly treat or dispose of oily waste in accordance with 907.e. 11/19/18</p> <p>Stained soil and possible leak in separator house, buckets of what appears to be crude oil, no containment see pic 6</p> <p>"For localized spotting of oily waste - ""Properly treat or dispose of oily waste in accordance with 907.e.""</p> <p>For larger instances: ""Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS"" 5/9/19</p> <p>Stained soil, possible leak on manifold. see pic 7</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 6/7/19</p> <p>No netting on produced water tank, hydrocarbon sheen appears to be visible on water see pic 8,9,11. No wildlife mortality was observed at time of inspection.</p> <p>Net or fence pit to prevent access per rule 902.d. 5/14/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	05/07/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100918	loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817431">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817431</a>