

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2019

Submitted Date:

05/07/2019

Document Number:

685100923**FIELD INSPECTION FORM**Loc ID 320071 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	
Condill, J.B.	303-680-4725	jbcrog@aol.com	
Canfield, Chris		chris.canfield@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202495	WELL	SI	06/01/2018	GW	001-07900	CHAMPLIN 485 AMOCO 1	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Submersible Pump

# 1

Comment: Submersible pump electric equip on cement pad by wellhead. see pic 1 &amp; 2, CA from previous inspection.

Corrective Action: Comply with Rule 603.f .

Date: 11/12/2018

Type: Bird Protectors

# 1

Comment: Bird protector appears to have fallen off of separator burner. see pic 6

Corrective Action: Install or repair wildlife protection equipment Comply with rule 324 A.a

Date: 05/17/2019

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 1

Comment: stained soil possible leak see pic 5

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 06/07/2019

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		39.557064,-104.090615

Comment: Tank is next to a county road. CA from previous inspection.

Corrective Action: Repair and paint tanks per Rule 804.

Date: 01/11/2019**Paint**

Condition: Inadequate

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Standing water in water tank containment, possible leak. see pic 7			
Corrective Action:	For a spill - "Recover free liquids and properly dispose in accordance with 907.c." For ineffective treatment of produced water entering a pit (may be used in addition to 902.c.) "Improve or correct treatment method to prevent crude oil or condensate from entering pit prior to any further discharge to pit to comply with rule 907.c."			Date: 05/08/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		39.557064,-104.090615

Comment:	Tanks are next to a county road, CA from previous inspection			
Corrective Action:	Repair and paint tanks per Rule 804.			Date: 01/11/2019

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	202495	Type:	WELL	API Number:	001-07900	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 113188Lat: 39.929853Long: -104.152468Reference Point: SE

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Pit does not have netting

Corrective Action

Net or fence pit to prevent access per rule 902.d.Date: 05/14/2019**Fencing:**Fencing Type: None

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/7/19 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at Champlin 485 Amoco 1 Renegade Oil and Gas company LLC 001-07900 in Adams County Colorado.</p> <p>While there, I observed Shut in well</p> <p>This is a follow up inspection from document # 688400397</p> <p>CA from previous inspection are delinquent and still need to be addressed.</p> <p>Bird protector appears to have fallen off of separator burner. see pic 6</p> <p>Install or repair wildlife protection equipment Comply with rule 324 A.a 5/17/19</p> <p>Submersible pump electric equip on cement pad by wellhead. see pic 1 &amp; 2, CA from previous inspection.</p> <p>Comply with Rule 603.f . 11/12/18</p> <p>stained soil possible leak see pic 5</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 6/7/19</p> <p>Tanks are next to a county road, CA from previous inspection(oil tanks)</p> <p>Repair and paint tanks per Rule 804. 1/11/19</p> <p>Tank is next to a county road. CA from previous inspection.(produced water tank)</p> <p>Repair and paint tanks per Rule 804. 1/11/19</p> <p>Standing water in water tank containment, possible leak. see pic 7</p> <p>For a spill - "Recover free liquids and properly dispose in accordance with 907.c." For ineffective treatment of produced water entering a pit (may be used in addition to 902.c.)</p> <p>"Improve or correct treatment method to prevent crude oil or condensate from entering pit prior to any further discharge to pit to comply with rule 907.c." 5/8/19</p> <p>Pit does not have netting</p> <p>Net or fence pit to prevent access per rule 902.d. 5/14/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>CEI</p>	medinaj	05/07/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100924	loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817434">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817434</a>