

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2019

Submitted Date:

05/07/2019

Document Number:

689703120

FIELD INSPECTION FORMLoc ID 334977 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258990	WELL	PR	07/31/2002	GW	045-07678	PUCKETT 13-6D	PR
258991	WELL	PR	03/29/2002	GW	045-07679	PUCKETT 23-6D	PR
259001	WELL	PR	05/31/2002	GW	045-07681	PUCKETT 41-12D	PR
259002	WELL	PR	05/04/2002	GW	045-07682	PUCKETT 44-1D	PR
259003	WELL	PR	07/31/2002	GW	045-07683	PUCKETT 42-12D	PR
259004	WELL	PR	08/29/2002	GW	045-07670	PUCKETT 14-6D	PR

General Comment:

Follow up to Inspection doc. # 689701596

COGCC Inspection Report Summary

On Tuesday 05/07/2019 at approximately 1115 hours, I, Inspector Mike Longworth, conducted a Follow up field inspection # 334977 at Caerus PUCKETT

14-6D, at Location # 334977 in Garfield County, Colorado.

While there, I observed Type of Operation: Production of wells

During this inspection the following previous compliance issues have been confirmed resolved: Labeling issues have been satisfactorily repaired. Photos 5,6,7,8

During this inspection the following possible compliance issues were observed:

Fluid in secondary containments. Photos 2,3,4

Install or repair required BMPs per Rule 1002.f.

Corrective date: 06/08/2019

Inspected Facilities									
Facility ID:	258990	Type:	WELL	API Number:	045-07678	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	258991	Type:	WELL	API Number:	045-07679	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	259001	Type:	WELL	API Number:	045-07681	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	259002	Type:	WELL	API Number:	045-07682	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	259003	Type:	WELL	API Number:	045-07683	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	259004	Type:	WELL	API Number:	045-07670	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Fluid in secondary containments

Comment:
 Corrective Action:

Date: 06/08/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Follow up to Inspection doc. # 689701596	longworm	05/07/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703121	Inspection 689703120 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817536