

Inspection Photos

Location Name: Puckett 31-23D
Location # 335383



Photo 1



Photo 2



Inspection Photos

Location Name: Puckett 31-23D
Location # 335383



Photo 3
Damaged waddles



Photo 4
Run off storm water flow on to and across location.

Inspection Photos

Location Name: Puckett 31-23D
Location # 335383



Photo 5
Shale, rock and sediment sloughing of cut slope against tank berm.



Photo 6
Shale, rock and sediment sloughing of cut slope against tank berm.