

# Inspection Photos

5/07/2019

Operator: WESTERN OPERATING COMPANY -  
95620

Location ID: 319767

Inspection Doc. Number: 696200002

Adams County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 1:** Photo taken from the south end of the tank battery location, facing north. Photo shows vegetation over the reclamation is predominantly undesirable weedy plant species.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 2:** Photo taken from the south end of the tank battery location, facing east. Photo shows overview of the location, and that the vegetation over the reclamation is predominantly undesirable weedy plant species.



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 3:** Photo taken from the battery location. Photo shows bindweed (*Convolvus arvensis*) appears to be establishing on the location. This is a Colorado State listed noxious weed. Previous inspections required operator to conduct noxious weed management.



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 4:** Photo taken from the battery location. Photo shows what appears to be bindweed (*Convolvus arvensis*) is establishing on the location. This is a Colorado State listed noxious weed. Previous inspections required operator to conduct noxious weed management.




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 5:** Photo taken from the battery location. Photo shows Canada thistle rosettes (*Cirsium arvense*) establishing on the location. This is a Colorado State listed noxious weed. Previous inspections required operator to conduct noxious weed management.



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 6:** See comments under photo 5.



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 7:** Photo taken from the battery location. Green vegetation observed in photo is undesirable weedy plant species observed throughout the location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 8:** Photo taken from the west end of the battery location, facing southwest. Photo shows access road that leads to the well location has not been reclaimed in accordance with 1000 series rules and corrective actions (compaction alleviation, re-contouring, regrading, etc..).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 9:** Photo taken from the access road west of the well location, facing south. Photo shows access road that leads to the well location has not been reclaimed in accordance with 1000 series rules and corrective actions (compaction alleviation, re-contouring, regrading, etc..).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 10:** Photo taken from the access road west of the well location, facing north. Photo shows access road that leads to the well location has not been reclaimed in accordance with 1000 series rules and corrective actions (compaction alleviation, re-contouring, regrading, etc..).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 11:** Photo taken from the east end of the location, facing north. Photo shows operator has failed to reclaim the entire location in accordance with 1000 series rules and corrective actions (re-contour/re-grade)



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 12:** Photo taken from the east end of the location, facing west. Photo shows operator has failed to reclaim the entire location in accordance with 1000 series rules and corrective actions (re-contour/re-grade)



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 13:** Photo taken from the south end of the location, facing south. Photo shows gully erosion on the fill slopes of the location. Hat for reference.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 14:** Photo taken from the east end of the location, facing north. See comments under photo 10.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 15:** Photo taken from the northeast end of the location, facing west. Photo shows operator has failed to reclaim the entire location in accordance with 1000 series rules and corrective actions (re-contour/re-grade)



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: WESTERN OPERATING COMPANY - 95620

Location ID: 319767



**Photo 15:** Photo taken from the northeast end of the location, facing south. Photo shows operator has failed to reclaim the entire location in accordance with 1000 series rules and corrective actions (re-contour/re-grade). Photo also shows erosion degradation on the cut slopes.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources