

Photo 1 – Motu East Location ID 439459
200 BBL Steel AST Removed
Corresponds to photo #9&10 of 4/15/2019 Inspection



Photo 2 – Motu East Location ID 439459
Crude oil liquid load out line reclaimed



Corresponds to photo 3 of
4/15/2019 inspection

Photo 3 – Motu East Location ID 439459
Stained soil outside containment at crude oil
loadout reclaimed.
Corresponds to photo 2&8 of 4/15/2019 inspection



Photo 4 – Motu East Location ID 439459
Stained soil around wellhead and pumpjack
reclaimed
Corresponds with photo 6&7 of 4/15/2019 inspection



Photo 5 – Motu East Location ID 43945
Capacity volumes marked on tanks
Corresponds with photo 2 of 4/15/2019 inspection



Photo 6 – Motu East Location ID 43945
Leaks within treater building reclaimed
Corresponds with photo 4&5 of 4/15/2019 inspection



Photo 7 – Motu East Location ID 43945
Leaks within treater building reclaimed
Corresponds with photo 4&5 of 4/15/2019 inspection

