

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2019

Submitted Date:

05/08/2019

Document Number:

687904729**FIELD INSPECTION FORM**Loc ID 333518 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87415**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**19 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214166	WELL	PR	11/11/1955	GW	067-05486	BONDAD 33-9 6	PR

General Comment:[Site inspection with photos at the end of this report. Inspection does not alleviate from prior corrective actions.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Posted on stairs at tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted on separator building.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on sign on separator building.

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds growing within 25 feet of fired vessel and need to be controlled.		
Corrective Action:	Comply with Rule 603.f.	Date:	05/18/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused catch pan for water haulers should be reconnected or removed.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/08/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Chain link fence around location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Compressor	# 1		
Comment:	Gathering compressor on location.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	Flowlines for 33-9 #6 are: 1-2" flowline from wellhead to separator. 1-2" flowline from separator to compressor separator building with meter run. 1-2" flowline from compressor separator building to offsite dogleg. 1-2" flowline from separator dump valve to produced water tank.		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	Flowlines for onsite gathering compressor are: 1-2" flowline from gathering system to compressor suction. 1-2" flowline from gathering line to produced water tank. 1-2" flowline from compressor scrubber dump valve to produced water tank. 1-2" flowline from compressor discharge to separator. 1-2" flowline from separator to offsite dogleg.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	1 on 33-9 #6 and 1 on gathering compressor.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLs	PBV STEEL		,
Comment:	125 BBL tanks with expanded metal screen top. Suction line from produced water tank has the catch pan removed. Suction line bull plug is laying on ground and small localized oily waste spotting has occurred from hose connections/disconnections.				
Corrective Action:	Comply with Rule 605.d. and Rule 907.e.				Date: 06/08/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 214166	Type: WELL	API Number: 067-05486	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Pass	spill prevention for methanol injection.
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904730	Unused equipment/oily waste	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818508
687904731	Weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818509
687904732	Weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818510