

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2019

Submitted Date:

05/09/2019

Document Number:

689401706**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 Heil, John _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gardner, Mike		mgardner@terraep.com	
Arauzo, Steven		steven.arauza@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

On April 30, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Spill ID 464253.

Operator reported a spill of produced water from a hole in a 12 inch water pipeline, located 1.6 miles south of the Crawford Trail Compressor Station. Approximately 100 BBLs of water was recovered by vac-truck and it is estimated that 30% of that volume was precipitation that was running into the excavation (Doc #402024312).

The pipeline was excavated and repaired prior to inspection date. The pipeline repair was visible inside an open fenced excavation on inspection date. The excavation measured approximately 90 feet by 30 feet wide by 25 feet deep (see photos). There were two soil stockpiles, north and south of the excavation. The stockpiled soil had earthen berms and were approximately 60 feet by 60 feet by 30 feet tall (see photos). Sidewalls and bottom of excavation around the pipeline were moist and there was a strong hydrocarbon odor at the time of the inspection.

The excavation is located in the path of a drainage that originates at the road (see photos). Waddles were placed to the east side of the excavation (down gradient) and in the drainage to the east (see photos).

Environmental**Spill/Remediation:**

Comment: Initial Form 19 (Doc# 402024312) lists a discovery date of 4/26/2019. As of 5/9/2019 COGCC has not recieved a Supplemental Form 19 for this spill.

Corrective Action: Submit a Supplemental Form 19 with required information per rule 906.b.

Date: 05/06/2019

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401714	20190430 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4819217