

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2019

Submitted Date:

05/09/2019

Document Number:

690003512

FIELD INSPECTION FORM

Loc ID 330703 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251683	WELL	PR	08/08/2003	GW	123-19486	SLATER 33-28	PA
426440	WELL	PR	06/01/2018	OW	123-34687	SLATER 34-28	PA
426443	WELL	PR	06/01/2018	GW	123-34689	SLATER 6-4-28	PA
426444	WELL	PR	06/01/2018	OW	123-34690	SLATER 44-28	PA
426445	WELL	PR	06/01/2018	OW	123-34691	SLATER 43-28	PA
426446	WELL	PR	07/24/2012	OW	123-34692	SLATER 4-4-28	PA
426447	WELL	PR	06/01/2018	GW	123-34693	SLATER 4-6-28	PA

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Other	# 1			
Comment:	Gather system riser remains. See photo			
Corrective Action:				Date: _____

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: _____

Flaring:

Type			
Comment:			
Corrective Action:			Date: _____

Inspected Facilities									
Facility ID:	<u>251683</u>	Type:	<u>WELL</u>	API Number:	<u>123-19486</u>	Status:	<u>PR</u>	Insp. Status:	<u>PA</u>
Facility ID:	<u>426440</u>	Type:	<u>WELL</u>	API Number:	<u>123-34687</u>	Status:	<u>PR</u>	Insp. Status:	<u>PA</u>
Facility ID:	<u>426443</u>	Type:	<u>WELL</u>	API Number:	<u>123-34689</u>	Status:	<u>PR</u>	Insp. Status:	<u>PA</u>
Facility ID:	<u>426444</u>	Type:	<u>WELL</u>	API Number:	<u>123-34690</u>	Status:	<u>PR</u>	Insp. Status:	<u>PA</u>
Facility ID:	<u>426445</u>	Type:	<u>WELL</u>	API Number:	<u>123-34691</u>	Status:	<u>PR</u>	Insp. Status:	<u>PA</u>
Facility ID:	<u>426446</u>	Type:	<u>WELL</u>	API Number:	<u>123-34692</u>	Status:	<u>PR</u>	Insp. Status:	<u>PA</u>
Facility ID:	<u>426447</u>	Type:	<u>WELL</u>	API Number:	<u>123-34693</u>	Status:	<u>PR</u>	Insp. Status:	<u>PA</u>

COGCC Comments		
Comment	User	Date
<p>On Thursday, May 9, 2019 at 09:35, I, Craig Carlile conducted an on-site inspection at: 330703 Operated by: Crestone</p> <p>While there I observed the following:</p> <p>API 05-123- 19486, Well has been plugged, Form 6 document number: 401651790</p> <p>API 05-123-34692, Well has been plugged, Form 6 document number: 401649461</p> <p>API 05-123-34691, Well has been plugged, Form 6 document number: 401730794</p> <p>API 05-123-34690, Well has been plugged, Form 6 document number: 401741257</p> <p>API 05-123-34687, Well has been plugged, Form 6 document number: 401735084</p> <p>API 05-123-34689, Well has been plugged, Form 6 document number: 401741289</p> <p>API 05-123-34693, Well has been plugged, Form 6 document number: 401730815</p> <p>Area is in cultivated field. Gathering system riser remains see photo attached.</p> <p>Weather, overcast with rain.</p> <p>Possible compliance issues observed: None: ?</p> <p>This is a summary of the inspection report.</p>	carlilec	05/09/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003513	Photo Riser	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4819221