

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2019

Submitted Date:

05/09/2019

Document Number:

688800514

FIELD INSPECTION FORM

Loc ID 325168 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87415

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105402	PIT	AC			-	IGNACIO 33-8 2	EI
214188	WELL	PR	01/01/1995	GW	067-05508	IGNACIO 33-8 2	EI

General Comment:

On April 24, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Logos Operating LLC Ignacio 33-8 #2. For the most recent field inspection report of this facility, please refer to document #688800495. The purpose of this site visit was to document the progress of REM #7297.

Location

Lease Road:

	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Location sign mounted to meter run shack.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type PIT		
Comment:	Orange safety fencing around excavation is in disrepair.		
Corrective Action:			Date:

Equipment:

					corrective date
Type: Gathering Line	# 1				
Comment:	Williams Field Services gathering line riser near SW corner of location.				
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Flow Line	# 1				
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 105402 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 214188 Type: WELL API Number: 067-05508 Status: PR Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Please refer to REM #7297 for more information regarding this pit closure remediation project.](#)

Corrective Action:

Date:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 105402 Lat: 37.129317 Long: -107.671254

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Historical pit associated with Ignacio 33-8 #2 (API #067-05508).

Corrective Action: Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action: Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action: Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
On April 24, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Logos Operating LLC Ignacio 33-8 #2. For the most recent field inspection report of this facility, please refer to document #688800495. The purpose of this site visit was to document the progress of REM #7297. Confirmation samples have reportedly been collected from the excavation. Fill dirt was stockpiled on location at the time of this inspection.	hughesjo	05/09/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800515	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4819439