

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2019

Submitted Date:

05/09/2019

Document Number:

685200582**FIELD INSPECTION FORM**
 Loc ID 392727 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10717Name of Operator: ARAMARK SPORTS & ENTERTAINMENT SERVICESAddress: 34879 HWY 160City: MANCOS State: CO Zip: 81328**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hediger, Brian		Hediger-Brian@aramark.com	All Inspections
Boersma, Jim		Boersma-Jim@aramark.com	All Inspections
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223813	WELL	DM	11/03/1954	GW	083-05222	HALLER 1	PR

General Comment:

Follow up inspection for corrective actions from inspection doc# 685200559. See also doc# 685200573 from flowline pressure test

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	above ground markers for active domestic flowline		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-903-7503

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	unused flowline capped but not buried, end is expose near expose area around well, deliery points which are no longer in use afre disconnected but not cut off below grade.		
Corrective Action:	follow up with flowline integrity engineers on abandonment of unused flowline and compliance with Form 44 reporting requirements per Rule 603.f and 1105.c and 1101.b (1)	Date:	12/17/2018
Type	OTHER		
Comment:	impated material excavated from wellhead area and cited in previous inspections stored in open metal drums near well but utside fencing.		
Corrective Action:	Complete dispose impacted material in approved manner portion of previous corrective action Doc#685200559, provide documentation of disposal in form of receipts or manifests to Field Inspection Supervisor Steve Labowskie	Date:	12/17/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	223813	Type:	WELL	API Number:	083-05222	Status:	DM	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass	Gravel	Pass	Material Handling And Spill Prevention		single wall metal containers with no spill prev

Comment: [current disturbance is a small footprint with wood fence. Impacted material from wellhead excavation stored near well in metal drums also a issue under stormwater rules, see "housekeeping" section for CA](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: _____

Current Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: _____ Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F) _____

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
	labowsks	05/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685200591	metal drum of impacted material	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4819820
685200592	wellhead and excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4819821
685200593	close up excavation and capped unused flowline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4819822