

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2019

Submitted Date:

05/09/2019

Document Number:

687904737

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection
312126 _____ Stewart, Joseph _____ 2A Doc Num: _____**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Operator Information:**OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208**Contact Information:**

Contact Name	Phone	Email	Comment
Roland, Kandis		kroland@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214662	WELL	PR	12/01/2018	GW	067-06266	TIFFANY EAST 2-17	PR
299610	WELL	PR	02/10/2010	GW	067-09647	TIFFANY EAST 3-17	PR

General Comment:

Site inspection of equipment on site. Photos at the end of this report.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Signs located on fence at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on sign at wellhead.		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pump Jack on well Tiffany East #3-17 Is not in use and the head has been pulled off and a plunger lift has been installed. If pumpjack is not going to be put back into use, it is considered unused equipment and needs to be removed.		
Corrective Action:	Comply with Rule 603.f.		Date: 08/09/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire around location.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Ancillary equipment	# 2		
Comment:	Wellheads		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 8		
Comment:	2-3" flowlines from wellhead to separator. 2-3" flowlines from separator to meter house. 2-2" flowlines from separator dump to offsite produced water gathering system. 2-4" flowlines from meter house to offsite fathering system.		
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:	See unused equipment CA under housekeeping.			
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 2			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 214662 Type: WELL API Number: 067-06266 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 299610 Type: WELL API Number: 067-09647 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	spill prevention for chemical injection.
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904739	Unused pumpjack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820145
687904740	Unused pumpjack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820146