

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2019

Submitted Date:

05/10/2019

Document Number:

679704014

**FIELD INSPECTION FORM**

Loc ID 398147 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 22315

Name of Operator: D &amp; D RESOURCES INC

Address: 2835 VILLA WAY #4

City: GRAND JUNCTION State: CO Zip: 81501

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Colby, Lou		lou.colby@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231219	WELL	PA	01/14/1999	OW	103-08888	EMERALD 246	TA

**General Comment:**

COGCC Inspection Report Summary.

On 5/9/2019 at approximately 17:00, inspector Rick Moran, conducted a follow up inspection at D & D Resources well Emerald 246 in Rio Blanco county of FIR documents:

- 1) 692400575 4/29/2018
- 2) 680102200 8/31/2017
- 3) 675102462 4/28/2016

During this inspection the following compliance issues were observed as uncompleted:

- 1) Unused equipment.
- 2) Debris.
- 3) Open tank latch.
- 4) Tank labels.
- 5) Well head sign.
- 6) Tank secondary containment.
- 7) Oily waste at valve connection.
- 8) MIT.

Additional compliance issues identified with this inspection:

- 1) Battery sign.

The well is not P&A as indicated in the COGCC database.

This is a summary of inspection report 679704014.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	not present		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	not present		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	not present		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: none

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near well head.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Oily waste at tank valve.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Unused wood boards.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	200 BBLs	STEEL AST		40.105580,-108.890980
Comment:	Tank #1. Hatch is open.				
Corrective Action:					Date:

**Paint**

Condition Inadequate

Other (Content)

Other (Capacity) 210 bbl						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Other						
Comment: No berm present.						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	200 BBLS	STEEL AST		40.105630,-108.890950	
Comment: Tank #2.						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity) ~200 bbl						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Comment: No berm present.						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	231219	Type:	WELL	API Number:	103-08888	Status:	PA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: Well is not P&A. No production history on record since 1999. No MIT.									
Corrective Action:									
Date:									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704015	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820898">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4820898</a>