

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2019

Submitted Date:

05/10/2019

Document Number:

696100880**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 310651 Evins, Bret 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296335	WELL	SI	02/01/2019	GW	123-26749	PEPPLER 17-12	SI

General Comment:[This is a WELL & BATTERY inspection.](#)[Well: SI](#)[Entire battery & equipment is shut-down.](#)[Centralized Battery serves 2 Location IDs \(310651, 310057\). \(1-well per location\).](#)

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Capacity Not Legible on condensate tanks. Refer to Rule 210.e (60 Days). See photo #2.			
Corrective Action:	Post Legible capacity on condensate tanks to comply w/ Rule 210.e.			Date: 07/09/2019
Emergency Contact Number:				
Comment:	Emergency number NOT posted at wellsite. Refer to Rule 210.b (30 Days). See photo #1.			
Corrective Action:	Post Emergency number at wellsite. Comply w/ Rule 210.b.			Date: 06/10/2019
Good Housekeeping:				
Type	OTHER			
Comment:	Stained soil below loadouts on East & West condensate tanks. Oily waste. Refer to Rule 907.e (30 Days). See photos #3, 4.			
Corrective Action:	Remove or remediate stained soil below tank loadouts to comply w/ Rule 907.e.			Date: 06/10/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel			
Corrective Action:				Date:
Equipment:				
			corrective date	
Type: Horizontal Heated Separator	# 1			

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tank VOCs. Pilots: OFF Shut-down.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (310651, 310057).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		40.489739,-104.465512

Comment:	Equalizer line connects condensate tanks.			
Corrective Action:				Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berms w/ produced H2O tank.			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 296335 Type: WELL API Number: 123-26749 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: SI. Observed production valves shut.
COGCC records indicate last prod: 01/2019.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 05/09/2019 at approximately 15:15 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: GREAT WESTERN OPERATING COMPANY LLC Location Name: PEPPLER-66N63W /17SWNW Location ID: 310651 Location County: Weld County, Colorado While there, I observed: Well(s) - 1: SI. Entire battery & equipment is shut-down. Centralized Battery serves 2 Location IDs (310651, 310057). Routine inspection.</p> <p>3: Corrective Actions observed. 1.) Emergency number NOT posted at wellsite. Refer to Rule 210.b (30 Days). See photo #1. Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 06/10/2019. 2.) Capacity Not Legible on condensate tanks. Refer to Rule 210.e (60 Days). See photo #2. Post Legible capacity on condensate tanks to comply w/ Rule 210.e. Corrective Action date: 07/09/2019. 3.) Stained soil below loadouts on East & West condensate tanks. Oily waste. Refer to Rule 907.e (30 Days). See photos #3, 4. Remove or remediate stained soil below tank loadouts to comply w/ Rule 907.e. Corrective Action date: 06/10/2019.</p> <p>Weather: Sporadic light rain. Damp conditions. This is a summary of the inspection report.</p>	evinsb	05/10/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100881	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4821058