

**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 1 Loc pic**



**Photo 2 electric cords laying in mud and water.**

**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 3 Chemical hose cam lock not properly taped or double lock cam lock**



**Photo 4 Chemical hose cam lock not properly taped or double lock cam lock. Possible spill or storm water issue.**



**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 5 loc pic**



**Photo 6 Improper chemical storage: Chemical's not covered.**

**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 7 Improper storage of grease. No secondary containment.**



**Photo 8 Spill release: unknown fluid in drill out tank containment.**



**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 9 Spill release: unknown fluid in drill out tank containment.  
Frac sand in and on berm. Inadequate containment.**



**Photo 10 Stained soil in and on berm.**

**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 11 Spill release: unknown fluid in drill out tank containment.**



**Photo 12 Build up of mud and water improper drainage and no BMP's in place to control sediment from leaving access road to location.**



**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 13 Build up of mud and water improper drainage and no BMP's in place to control sediment from leaving access road to location.**



**Photo 14 Storm water: no BMP's in place to control sediment from leaving access road to location. Sediment is running off and covering vegetation.**

**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 15 Storm water: no BMP's in place to control sediment from leaving access road to location. Sediment is running off and covering vegetation.**



**Photo 16 Storm water: no BMP's in place to control sediment from leaving access road to location.**



**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 15 Tracking pad: Rock tracking pad impacted with sediment not properly maintained.**



**Photo 16 Tracking pad: Rock tracking pad impacted with sediment not properly maintained.**



**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 17 Tracking pad**



**Photo 18 Vehicle tracking: Sediment from access road being carried onto HWY 7 .**



**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 19 Vehicle tracking: Sediment from access road being carried onto HWY 7 .**



**Photo 20 Vehicle tracking: Sediment from access road being carried onto HWY 7 .**

**Inspection Photos**  
**Location Name: B-Farm LD 18-392HN**  
**Location ID: 452914**



**Photo 21 Storm water Improper BMP's sediment being carried off access road into vegetation.**



**Photo 22 Storm water Improper BMP's sediment being carried off access road into vegetation.**