

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2019

Submitted Date:

05/13/2019

Document Number:

685100937**FIELD INSPECTION FORM**
 Loc ID 319912 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
,		dnr_cogccengineering@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201870	WELL	TA	03/01/2018	GW	001-07274	SIMPSON A 8	TA

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipmet, PU is not connected to well head horses head is gone. No tubing or rods		
Corrective Action:	Comply with Rule 603.f .	Date:	01/01/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 201870 Type: WELL API Number: 001-07274 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: PU is not hooked to WH tubing and rods are gone. Well is not plumbed to flow line.  
According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to  
be TEMPORARILY ABANDON.

Corrective Action: According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to  
be TEMPORARILY ABANDON.  
Well must have a successful mechanical integrity test performed or plugged as directed  
by Rule 319 b (3)

Date: 10/14/2018

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/13/19 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at Fritzler Resources INC Linnebur 24-1 001-08525 in Adams County Colorado.</p> <p>While there, I observed Temporarily Abandoned well</p> <p>This is a follow up inspection from document # 688400348</p> <p>All CA are delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipmet, PU is not connected to well head horses head is gone. No tubing or Rods 1/1/19</p> <p>PU is not hooked to WH tubing and rods are gone. Well is not plumbed to flow line.</p> <p>According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON.</p> <p>According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON.</p> <p>Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3) 10/14/18</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	05/13/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402043337	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822549">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822549</a>
685100938	loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822472</a>