

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate but starting to fad may need to be replaced in near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	square tubing and hog wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electric panel steel rod		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Ancillary equipment		# 1		
Comment:	Electric panel			
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:	appears to be plumbed to surface			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240299 Type: WELL API Number: 123-08087 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection	silverr	05/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688402175	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822974