

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2019

Submitted Date:

05/08/2019

Document Number:

688800512**FIELD INSPECTION FORM**

Loc ID 312001 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216576	WELL	PR	02/16/2004	GW	067-08182	HARMON 1A	EI
288175	WELL	PR	12/01/2006	GW	067-09272	IGE 110	EI
433111	WELL	PR	06/19/2018	GW	067-09895	IGE 140	EI

General Comment:

On April 22, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC IGE #140. For the most recent field inspection report of this facility, please refer to document #680602776. The purpose of this site visit was to inspect the location of complaint #200447060.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	ASTs are labeled with contents, capacity, and have NFPA placards.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Free standing signs near each wellhead on location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Lube Oil	WELLHEAD	<= 1 bbl		
Comment:	Stained wellhead and area surrounding wellhead.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 06/07/2019
Lube Oil	Truck Loadout	<= 1 bbl		
Comment:	Stained soil along western side of IGE #140 pump jack.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 06/07/2019
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Guard fencing on pump jacks.			
Corrective Action:				Date:
Equipment:				
Type: Vertical Heated Separator	# 2			corrective date
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Domestic tap.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		37.099711,-107.746508
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
--------	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: <u>216576</u>	Type: <u>WELL</u>	API Number: <u>067-08182</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>288175</u>	Type: <u>WELL</u>	API Number: <u>067-09272</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>433111</u>	Type: <u>WELL</u>	API Number: <u>067-09895</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Environmental**Spills/Releases:**

Type of Spill:	_____	Estimated Spill Volume:	_____
Comment:	<div></div>		
Corrective Action:	<div></div>		Date: _____
Reportable:	_____	GPS: Lat _____	Long _____
Proximity to Surface Water:	_____	Depth to Ground Water:	_____

Water Well Complaint:

			Lat	Long
DWR Receipt Num:	199450	Owner Name:	Alonzo	GPS : 37.098303 -107.747633

Field Parameters:

Sample Location:	_____	Comment:	_____
------------------	-------	----------	-------

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil container on secondary containment.
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Drip pot on valve near domestic tap.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On April 22, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC IGE #140. For the most recent field inspection report of this facility, please refer to document #680602776. The purpose of this site visit was to inspect the location of complaint #200447060. During this inspection stained soil was observed around the IGE #140 wellhead and along the western side of the pump jack at the IGE #140.	hughesjo	05/08/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402037093	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818670
688800513	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818649