

Inspection Photos
Operator: Catamount Energy
Location/API #: 067-08284
Date: 5-9-2019



Photo 1. View of disturbance area in the western project area, needing stormwater controls and reclamation.



Photo 2. Downslope of disturbance area in the western project area where soil was pushed down-slope. Sediment controls are needed here.



Photo 3. View of metal debris within the project area.



Photo 4. View of Russian knapweeds (*Rhaponticum repens*) within the northern project area.



Photo 5. View of erosional channeling at the well pad entrance, and along the access road. BMPs are not sufficient in this area. Road was recently improved, appears to have been crowned, graveled, and ditched.