

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2019

Submitted Date:

05/15/2019

Document Number:

679704060

FIELD INSPECTION FORM

Loc ID 314283 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 22370
Name of Operator: D & G ROUSTABOUT SERVICE
Address: 765 S 1/2 ROAD
City: MACK State: CO Zip: 81525

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Terrell, David	970-216-6929	terrelloil@aol.com	All inspections
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228192	WELL	SI	10/01/2017	GW	103-05005	SLOAN-GOVERNMENT 1	SI

General Comment:

[COGCC Inspection Report Summary.](#)

On 5/14/2019 at approximately 15:00, inspector Rick Moran, conducted a routine inspection at D&G Roustabout Service's well Governement Sloan 1 in Rio Blanco county.

The location was reached by traveling from the east (CR 118) and departing to the west (CR 109). The least washout BLM roads to reach the location is from CR 109.

During this inspection the following compliance issues were observed:

- 1) Empty container on pallets & motor oil containers stored on ground. Photo 2 & 3.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704060.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	970-858-1581		Date: _____
Corrective Action:			

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Empty container of corrosion inhibitor without secondary containment on pallets. Two 1 gallon containers of motor oil stored on ground without secondary containment.		
Corrective Action:	Comply with Rule 603.f .		Date: 06/17/2019

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	Open Top		39.686870,-108.937050	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	~10 bbl				

Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities

Facility ID: 228192 Type: WELL API Number: 103-05005 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last recorded production September 2017. Casing pressure gage 280 psi at time of inspection.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704061	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823615