

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/15/2019

Document Number:

696200050

FIELD INSPECTION FORM
 Loc ID 454195 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10657

Name of Operator: PCR OPERATING LLC

Address: 4040 BROADWAY STREET #510

City: SAN ANTONIO State: TX Zip: 78209

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		denise.arthur@state.co.us	
		dkunovic@passcreekresource s.com	
		gwehrer@passcreekresource s.com	
		sguzman@passcreekresourc es.com	
Pesicka, Conor		conor.pesicka@state.co.us	
		cryan@passcreekresources.c om	
		dnr_cogccengineering@state. co.us	
		dnr_cogccenforcement@state .co.us	
		bramirez@passcreekresource s.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454195	LOCATION	AC	03/05/2018		-	ADENA SOUTH WATER PLANT 158-24-41	RI

General Comment:

This is a follow-up good housekeeping, interim reclamation and stormwater inspection to doc. #696200040.

This inspection is to document compliance for the following corrective actions:

210.d: Signage at battery

912.b: Venting of gas

605.a(4): Secondary containment around tanks

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Previous inspection documented insuddicient signage missing on tanks. Operator has installed signage on tanks in accordance with 210.d		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	#		
Comment:			
Corrective Action:	Gas freely venting from the meter run on the west end of the location. Operator submitted sundry doc. #402041764 on 5/13/2019 with request to vent. Sundry currently "in process".		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment remains inadequate around tank(s)			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date:

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 454195 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200051	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823683