

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2019

Submitted Date:

05/15/2019

Document Number:

689802641**FIELD INSPECTION FORM**Loc ID 316763 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 3250Name of Operator: ANTELOPE ENERGY COMPANY LLCAddress: P O BOX 577City: KIMBALL State: NE Zip: 69145**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Keeler, Jodi	308-235-4661	jodik@antelope-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232713	WELL	SI	01/06/2015	OW	107-06127	STATE OF COLORADO 1-16	SI

General Comment:[COGCC Inspection 689802641 Report Summary](#)

On Wednesday 05/08/2019 at approximately 11:00, I, Inspector Emily Waldron, conducted a MIT and Bradenhead Test witness at Antelope Energy Company LLC State of Colorado 1-16, at 05-107-06127 in Routt County, Colorado.

While there, I observed a MIT and Bradenhead Test. The MIT held 400 psi for 15 minutes. Test was passed in the field. The Bradenhead had 3 psi for 30 minutes.

This is a summary of inspection 689802641 report.

Inspected FacilitiesFacility ID: 232713 Type: WELL API Number: 107-06127 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Inspector on location to witness MIT and bradenhead test. Form 42 document number 402013332. Pakcer not within 100 feet of perfs due to slotted liner not cemented. Casing pressured to 400 psi and held for 15 minutes. Test passed in field. Bradenhead had 3 psi for 30 minutes.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689802654	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823682