

**FRAM OPERATING LLC – 10310**  
**API # 05-077-08864 JENSEN #12-1**  
**Inspection Date : 05/13/2019**



**Overview of location from SE corner of pad  
looking W**



**Shut in wellhead with sign. Locked out/Tagged out.**



**FRAM OPERATING LLC – 10310**  
**API # 05-077-08864 JENSEN #12-1**  
**Inspection Date : 05/13/2019**



**8' Gathering line riser. Blind flanged and  
Locked out/Tagged out**



**4" & 2" Production line riser. Blind flanged and  
Locked out/Tagged out.**



**FRAM OPERATING LLC – 10310**  
**API # 05-077-08864 JENSEN #12-1**  
**Inspection Date : 05/13/2019**



**65 BBL Produced water tank with earth berms. No connections, Not in service.**



**Separator and Meter housing.**

**FRAM OPERATING LLC – 10310**  
**API # 05-077-08864 JENSEN #12-1**  
**Inspection Date : 05/13/2019**



**Staining of soil at base of Separator from  
previously repaired leak.**



**Overview of location from Kannah Creek Rd.  
looking NW**