

Inspection Photos

Operator: Catamount Energy
Location/API #: 067-09578
Date: 5-9-2019



Photo 1. View of revegetation within the northern project area.



Photo 2. Downslope of rilling along the southeastern edge of the project area.



Photo 3. View sediment discharge from the eastern edge of the project area , and wattles filled with sediment.



Photo 4. View of Russian knapweeds (*Rhaponticum repens*) along the eastern edge of the working area.



Photo 5. View of erosional channeling along the access road.



Photo 6. View of erosion where stormwater flows from the access road bisect the culvert outlet.