

Inspection Photos
Location Name: Redwin 22-4
Location ID: 307168



Wellhead



Tubing pressure

Inspection Photos
Location Name: Redwin 22-4
Location ID: 307168



Casing pressure



Bradenhead pressure