

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402046077

Date Received:

05/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Church, Matt	405-651-6853	mchurch@sandridgeenergy.com
Neidel, Kris		kris.neidel@state.co.us
		sandridgeenvironmental@sandridgeenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400970
Inspection Date: 05/08/2019 FIR Submit Date: 05/14/2019 FIR Status:

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC Company Number: 10598
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 447512

Location Name: Open Range Number: 18 County:
Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.571594 Longitude: -106.424475

FACILITY - API Number: 05-057-00 Facility ID: 447512

Facility Name: Open Range Number: 18
Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6
Latitude: 40.571594 Longitude: -106.424475

CORRECTIVE ACTIONS:

1 CA# 125144

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.
24 hours to remove free fluids. 30-days to remove stained soil.

Date: 05/15/2019

Response: CA COMPLETED Date of Completion: 05/13/2019

Mouse holes were backfilled and capped. All fluids were removed via hydro vac prior to backfill and capping.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 125145

Corrective Action: Stabilize stockpiled soil with appropriate BMPs or remove from site if determined by identification to be necessary.

Date: 05/29/2019

Response: CA COMPLETED

Date of Completion: 05/13/2019

Operator
Comment:

Piles were of snow and base material from clearing pad of snow. Piles were spread out so ice and snow could melt.

COGCC Decision:

COGCC
Representative:

3 CA# 125146

Corrective Action: Protect and stabilize with appropriate BMPs, stockpiled soil.

Date: 05/29/2019

Response: CA COMPLETED

Date of Completion: 05/13/2019

Operator
Comment:

Piles were of snow and base material from clearing pad of snow. Piles were spread out so ice and snow could melt.

COGCC Decision:

COGCC
Representative:

4 CA# 125147

Corrective Action: Close/backfill two open mouse holes.
CA Date given is thirty days past date of Release of Drilling Rig.

Date: 12/24/2018

Response: CA COMPLETED

Date of Completion: 05/13/2019

Operator
Comment:

Mouse holes were backfilled and capped. All fluids were removed via hydro vac prior to backfill and capping.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Church

Signed:

Title: EHS Specialist

Date: 5/16/2019 8:05:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files