

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2019

Submitted Date:

05/14/2019

Document Number:

687904745

FIELD INSPECTION FORM

Loc ID 333566 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 14 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Azulai, .	970-563-4000	maralextech@gmail.com	all inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214932	WELL	SI	09/01/2017	GW	067-06537	SHELHAMMER 1	SI

General Comment:

[Site inspection with photos at the end of this inspection report. Facility inspection for decomissioned compressor and dehydrator equipment for waste disposal and removal following this report.](#)

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Handwritten tank information posted on tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information posted on sign.		Date: _____
Corrective Action:			

Good Housekeeping:			
Type	TRASH		
Comment:	Trash in meter house that is infested with mice and packrats needs to be removed.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/16/2019
Type	WEEDS		
Comment:	Weeds surrounding wellhead and separator need to be controlled.		
Corrective Action:	Control weeds to comply with Rule 603.f.	Date:	06/16/2019
Type	UNUSED EQUIPMENT		
Comment:	Sound panels from compression facility are sitting right next to separator and are being unused.		
Corrective Action:	Unused equipment needs to be removed from location per Rule 603.f.	Date:	06/16/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to gathering system.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Bradenhead plumbed to surface.	Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Located in meter house.	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Appears berm capacity will not hold volume of one tank plus stormwater/rain event. Berm should be built up to reflect proper secondary containment volumes. Control weeds in secondary containment.			
Corrective Action:	Raise berm to comply with Rule 906.d.(1) and Rule 605.a.(4) and Control weeds to comply with Rule 603.f.			Date: 06/16/2019

Venting:

Yes/No	NO	Date:	
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 214932 Type: WELL API Number: 067-06537 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in and not producing. No LOTO on wellhead or separator or meter tube.

Corrective Action: Produce well after performing successfull Mechanical integrity test or plug and abandoned well.

Date: 05/15/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904795	SHELHAMMER 1 Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825260