

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

687904763**FIELD INSPECTION FORM**
 Loc ID 325560 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Azulai, .	970-563-4000	maralextech@gmail.com	<a href="#">all inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215004	WELL	PR	08/28/2006	GW	067-06609	HEIKKINEN 1-10	PR

**General Comment:**[Site inspection with photos at the end of this report.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Gravel access road through locked gate.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign posted at wellhead.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on sign.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Weeds and vegetation around separator and wellhead need to be controlled.			
Corrective Action:	Comply with Rule 603.f.			Date: 06/16/2019
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Cattle panels around separator.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panels around wellhead.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Ancillary equipment	# 1			corrective date
Comment:	Wellhead.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	On separator stack.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	1-2" flowline from wellhead to separator. 1-2" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg. 1-2" flowline from separator to produced water gathering system.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	FIBERGLASS AST		,
Comment:	Open top fiberglass tank with wildlife bird netting. Netting has holes and is not serving purpose for protecting wildlife from entering tank.				
Corrective Action:	Comply with Rule 324 A.a				Date: 05/23/2019

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment berm has tire tracks through it and berm is not definite with walls that will contain a spill.			
Corrective Action:	Comply with Rule 906.d.(1).			Date: 06/14/2019

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 215004	Type: WELL	API Number: 067-06609	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing.			
Corrective Action:				Date:

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904789	HEIKKINEN 1-10 Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825263">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825263</a>