

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

687904777**FIELD INSPECTION FORM**

Loc ID 311958 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277813	WELL	PR	01/10/2006	GW	067-09049	MARY CATHERINE 33-7-3 2A	PR
294238	WELL	PR	05/11/2008	GW	067-09476	MARY CATHERINE 33-7-3 3C	PR

General Comment:[Site inspection with photos at the end of this inspection report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road access through locked gate.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Signs posted on meter house.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds around equipment need to be controlled.			
Corrective Action:	Comply with Rule 603.f.			Date: 06/16/2019
Type	UNUSED EQUIPMENT			
Comment:	Unused wellhead valve sitting on pump jack skid needs to be removed.			
Corrective Action:	Comply with Rule 603.f.			Date: 06/16/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Pump Jack	#			corrective date
Comment:	33-7-3 #2A and #3C both have gearbox seal leaks on pumpjack and stained soil and oily waste are present along concrete.			
Corrective Action:	Comply with Rule 605.d. and Rule 907.e.			Date: 06/14/2019
Type: Bird Protectors	# 2			
Comment:	On separator stacks.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 9			

Comment:	2-2" flowlines from wellhead to separator. 2-3" flowlines from separator to meter house. 2-3" flowlines from meter house to offsite dogleg. 2-2" flowlines from separator dump valves to produced waater gathering system. 1-1" flowline from separator to pumpjack fuel gas.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	PVC bradenhead access.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	Wellhead has localized areas of stained soil and gravel and oily waste. Treat and dispose of properly.			
Corrective Action:	Comply with Rule 907.e. and Rule 1002.f.(2)		Date:	06/16/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 277813 Type: WELL API Number: 067-09049 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 294238 Type: WELL API Number: 067-09476 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	No spill prevention for engine oil day tanks.
Gravel	Pass	Gravel	Pass			

Comment: [Pump jack engine oil day tanks do not have spill prevention. Implement and maintain Best Management Practices \(BMP's\) to include measures such as spill prevention.](#)

Corrective Action: [Comply with Rule 1002.f.\(2\)B](#)

Date: 06/16/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904791	MARY CATHERINE 33-7-3 2A Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825265