

Inspection Photos

API: 05-061-06296

Operator: STRACHAN EXPLORATION INC

Inspection Date: 5/15/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06296 | Date: 5/15/2019

Inspection Photos



Photo 1. It appears water pools onto the access road. A new road has been made by vehicles avoiding this area when wet causing additional disturbance that needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06296 | Date: 5/15/2019

Inspection Photos



Photo 2. There is oil stained soil near the outlet of the tank shown in the photo. No containment present.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06296 | Date: 5/15/2019

Inspection Photos



Photo 3. There is oil stain soil around the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06296 | Date: 5/15/2019

Inspection Photos



Photo 4. This appears to be unused equipment stored at the site. A 5 gallon bucket is underneath equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06296 | Date: 5/15/2019

Inspection Photos



Photo 5. There is oil dripping off the hose that goes into the tank. No secondary containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06296 | Date: 5/15/2019

Inspection Photos



Photo 6. The fence around the equipment is insufficient to prevent livestock entry. There is a roll of barbed wire left on the H brace.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06296 | Date: 5/15/2019