

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2019

Submitted Date:

05/16/2019

Document Number:

689900685

FIELD INSPECTION FORM

Loc ID 324823 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212935	WELL	PR	07/01/2017	GW	061-06296	FRAZEE 1-6	RI

General Comment:

[Location and Stormwater inspection.](#)

Location			
Lease Road:			
Type	Access		
comment:	See stormwater section. Corrective action required.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	There is role of barbed wire on the H brace.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>06/15/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	There is a unused tank trailer on location.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>06/15/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	Pump Jack		
Comment:	907.e. Oily Waste. There is oil stained soil at the well head. There is also staining at the tank outlet and hose. No secondary containment. See Photos		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS		Date: <u>05/20/2019</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	The fence around the equipment are insufficient to prevent livestock entry.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		Date: <u>06/15/2019</u>
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The access road is not maintained and does not adequately drain stormwater. As a result, vehicles are traveling outside of the access road creating significant disturbance and soil compaction. See Attached Photos

Corrective Action: Prevent vehicle disturbance outside of the access road and reclaim disturbance. Properly grade and install road base to allow stormwater draiange. Install or repair required BMPs per Rule 1002.f.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900686	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825399