

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2019

Submitted Date:

05/16/2019

Document Number:

696100902

FIELD INSPECTION FORM

Loc ID 306312 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287755	WELL	PR	05/01/2018	GW	123-24412	CACHE 8-34	SI

General Comment:

This is a WELL & BATTERY inspection.
Well: Shut-In (SI).
Entire battery & equipment is shut-down.
Centralized Battery serves 6 Location IDs (306312, 306310, 306311, 309823, 309973, 419186). (1-well per location).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Methanol: Placarded.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	<p>From prior insp: Trash (Bucket with oily fluid, oily rag, old tools, fittings) inside of east separator doghouse. Refer to Rules 603.f & 907.e for guidance. Remove trash & oily waste in bucket. Comply with Rule 603.f & 907.e. The previous CA date for this from FIR #691200244 dated 7/11/2018 remains applicable. Original Corrective Action date: 07/23/2018.</p> <p>This insp: * Trash (Bucket with oily fluid, oily rag, old tools, fittings) inside of east separator doghouse has been removed.</p>		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	1: ECD scrubber. 1: Methanol pump, metal tank (Placarded), drip containment		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:	Controls crude oil tanks VOCs. Pilots: OFF Shut-down.		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		

Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 5	
Comment:	1: Master / Primary gas meter run. 4: Secondary gas meter runs.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 6 Location IDs (306312, 306310, 306311, 309823, 309973, 419186).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	150 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ condensate tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	300 BBLS	STEEL AST		40.499062,-104.461664
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O vault.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 287755 Type: WELL API Number: 123-24412 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Observed production valves shut.
COGCC records indicate last prod: 02-2019.

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
COGCC Inspection Report Summary: On THU 05/16/2019 at approximately 12:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: GREAT WESTERN OPERATING COMPANY LLC Location Name: CACHE-66N63W /8SWSE Location ID: 306312 Location County: Weld County, Colorado While there, I observed: Well(s) - 1: Shut-In (SI). Entire battery & equipment is shut-down. Centralized Battery serves 6 Location IDs (306312, 306310, 306311, 309823, 309973, 419186). Follow-up Inspection. Follow-up to Field Inspection Report Doc #691200425 dated 09/07/2018. 1 of 1: Corrective Actions appear addressed. 1.) Trash (Bucket with oily fluid, oily rag, old tools, fittings) inside of east separator doghouse. Refer to Rules 603.f & 907.e for guidance. Remove trash & oily waste in bucket. Comply with Rule 603.f & 907.e. The previous CA date for this from FIR #691200244 dated 7/11/2018 remains applicable. Original Corrective Action date: 07/23/2018. * Trash (Bucket with oily fluid, oily rag, old tools, fittings) inside of east separator doghouse has been removed. NO: Corrective Actions observed on this inspection. This is a summary of the inspection report.	evinsb	05/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100903	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825534