

Inspection Photos

API: 05-061-06397

Operator: BERRY ENERGY INC

Inspection Date: 5/15/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06397 | Date: 5/15/2019

Inspection Photos



Photo 1. Facing south toward the location. There is a bare area with no vegetation growth approximately 100 ft. x 60 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06397 | Date: 5/15/2019

Inspection Photos



Photo 2. There is a pipe riser that remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06397 | Date: 5/15/2019

Inspection Photos



Photo 3. Facing south toward the location. There is predominately undesirable weeds (Kochia) in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06397 | Date: 5/15/2019

Inspection Photos



Photo 4. View of undesirable weeds growing at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06397 | Date: 5/15/2019

Inspection Photos



Photo 5. Facing east at the south side of location. Vegetation has not established in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06397 | Date: 5/15/2019

Inspection Photos



Photo 6. Facing toward the surrounding undisturbed pasture which contains Bou gra, Spo cry, Oli ari, Pas smi, among other native plants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06397 | Date: 5/15/2019