

Inspection Photos  
Location Name: CC 604-12-13 Annex  
Location ID 424970



Location ID 424970 Entrance sign.



Location ID 424970 Active drilling location.

Inspection Photos  
Location Name: CC 604-12-13 Annex  
Location ID 424970



Location ID 424970 Track-hoe spreading material over what appeared to be drill cuttings.



Location ID 424970 Track-hoe spreading material over what appeared to be drill cuttings.