

**Inspection Photos**  
**Location Name: CC 697-03-07Pad**  
**Location ID 452807**



**Location ID 452807 Entrance sign.**



**Wooden pallet debris.**

**Inspection Photos**  
**Location Name: CC 697-03-07Pad**  
**Location ID 452807**



**Oil Stained soil with trash/debris near frac tank.**



**Oil stained soil, uncapped, unmarked riser.**

**Inspection Photos**  
**Location Name: CC 697-03-07Pad**  
**Location ID 452807**



**Diesel ASTs inside of secondary containment. Note drill cutting stock pile on hill behind ASTs.**



**Three 55-gallon containers, one on its side.**

Inspection Photos  
Location Name: CC 697-03-07Pad  
Location ID 452807



Oil stained soil.



Oil stained soil.

**Inspection Photos**  
**Location Name: CC 697-03-07Pad**  
**Location ID 452807**



**Pumping operations at tank battery**



**Oil staining at nearly all well heads.**

**Inspection Photos**  
**Location Name: CC 697-03-07Pad**  
**Location ID 452807**



**Unmarked, uncapped riser previously mentioned.**



**Food debris at base of concrete jersey barrier.**